

# WINSLOW TRESTLE TABLE ASSEMBLY INSTRUCTIONS

---

**Tools needed:**

Allen wrench (provided)  
Mallet


**Hardware included:**

8 bolts  
8 plugs

**Parts included:**

1 Table top  
1 Trestle  
2 Base parts (legs)

1. Place the ends of the trestle through the openings in the base parts. Make sure the base parts both have the large counterbores on the outside of the assembly.
2. Insert bolts through the large counterbored holes in the base and into the threaded inserts in the corresponding holes in the trestle. Tighten them snugly but not all the way.
3. Place the table base upright on the floor where it will stand and tighten all of the bolts using the Allen wrench. When done, the base should be sitting flat on the floor and not rock. If it rocks, loosen the bolts and let it settle onto the floor and retighten.
4. Add the table top: using the bolts supplied, attach the battens on the table to the upright bases. If the base was aligned properly with the floor, the table will not move or rock. If there is any rocking, loosen all bolts and allow the table to settle to the floor and retighten. There is enough allowance in the holes to allow you to align the table to any floor.
5. Use the large wooden plugs to cover the visible holes on the outsides of the base legs. Start the plugs into the counterbored holes on the base and, using a flat piece of wood or other material tap them home with a hammer or mallet. The wooden plate will allow you to tap the plugs flush with the surface and not mar the wood. When properly inserted, they will be almost invisible, especially if you take the time to line up the grain on the plugs with the grain on the legs.



NOTE: You will have to destroy the plugs to disassemble the base. We have supplied enough plugs to disassemble and reassemble once, although you may wish to move the base without taking it apart to avoid this issue.

---

Vermont Handcrafted Furniture / Vermont Furniture Designs

WWW.VERMONTFURNITUREDESIGNS.COM

Made in the USA

